



# Notification of Hazardous Waste Site

United States  
Environmental Protection  
Agency  
Washington DC 20460

5-4-82

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

RECEIVED

WHZ/F 1.3 U1

JUN 17 '82

EPA # WAD009041450

A. marked

6-1-82 82-06-14

Solid Waste Mgmt.  
EPA Region X

WAS 000001232

## A Person Required to Notify:

Enter the name and address of the person or organization required to notify.

Name WEYERHAEUSER COMPANY

Street P.O. Box 188

City LONGVIEW

State WASH Zip Code 98632

## B Site Location:

Enter the common name (if known) and actual location of the site.

Name of Site CHLOR-ALKALI PLANT - WEYERHAEUSER MILLSITE

Street INDUSTRIAL WAY

City LONGVIEW County Cowlitz State WASH Zip Code 98632

## C Person to Contact:

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.

Name (Last, First and Title) KEN JOHNSON - REGION ENVIRONMENTAL ENGINEER

Phone (206) 425-2150

## D Dates of Waste Handling:

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year) 1956 To (Year) 1974

## E Waste Type: Choose the option you prefer to complete

**Option 1:** Select general waste types and source categories. If you do not know the general waste types or sources, you are encouraged to describe the site in Item I—Description of Site.

**General Type of Waste:**  
Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.

- 1. ☐ Organics
- 2. ☐ Inorganics
- 3. ☐ Solvents
- 4. ☐ Pesticides
- 5. ☒ Heavy metals
- 6. ☐ Acids
- 7. ☐ Bases
- 8. ☐ PCBs
- 9. ☐ Mixed Municipal Waste
- 10. ☐ Unknown
- 11. ☐ Other (Specify)

**Source of Waste:**  
Place an X in the appropriate boxes.

- 1. ☐ Mining
- 2. ☐ Construction
- 3. ☐ Textiles
- 4. ☐ Fertilizer
- 5. ☐ Paper/Printing
- 6. ☐ Leather Tanning
- 7. ☐ Iron/Steel Foundry
- 8. ☒ Chemical, General
- 9. ☐ Plating/Polishing
- 10. ☐ Military/Ammunition
- 11. ☐ Electrical Conductors
- 12. ☐ Transformers
- 13. ☐ Utility Companies
- 14. ☐ Sanitary/Refuse
- 15. ☐ Photofinish
- 16. ☐ Lab/Hospital
- 17. ☐ Unknown
- 18. ☐ Other (Specify)

**Option 2:** This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).

**Specific Type of Waste:**

EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located.

|      |
|------|
| D009 |
|      |
|      |
|      |
|      |
|      |
|      |
|      |
|      |
|      |

|  |
|--|
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |

|  |
|--|
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |

USEPA SF



1457558



# Notification of Hazardous Waste Site

Side Two

## F Waste Quantity:

Place an X in the appropriate boxes to indicate the facility types found at the site.

In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.

In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

## Facility Type

1. ☐ Piles
2. ☐ Land Treatment
3. ☒ Landfill
4. ☐ Tanks
5. ☐ Impoundment
6. ☐ Underground Injection
7. ☐ Drums, Above Ground
8. ☐ Drums, Below Ground
9. ☐ Other (Specify) \_\_\_\_\_

## Total Facility Waste Amount

cubic feet 2000 cu. yds. (Y)

gallons \_\_\_\_\_

## Total Facility Area

square feet 45,000 ft<sup>2</sup> (S)

acres \_\_\_\_\_

## G Known, Suspected or Likely Releases to the Environment:

Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☐ Known ☒ Suspected ☐ Likely ☐ None

Note: Items Hand I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

## H Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.



## I Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

Mercury cells were utilized in the production process from 1956-74. Periodic maintenance and cell replacement produced a variety of waste materials having a very slight mercury contamination. As these materials were generated, they were piled in two areas adjacent to the production operations (see locations on map above) and subsequently covered over with river dredge spoils. Two wells, supplying water for process use only, are located adjacent to the westernmost disposal site.

## J Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other".

Name

Tom Steiner

Street

Weyerhaeuser Co, P.O. Box 188

City

Longview

State

WA

Zip Code

98632

Signature

Tom Steiner

Date

5/4/82

☒ Owner, Present

☒ Owner, Past

☐ Transporter

☒ Operator, Present

☒ Operator, Past

☐ Other



*Mike*  
*[Signature]*  
**Weyerhaeuser Company**

Tacoma, Washington 98477  
(206) 924-2345

June 14, 1982

Ms. Linda Dawson  
Hazardous Waste Division  
Environmental Protection Agency  
Region X  
1200 Sixth Avenue  
Seattle, Wa., 98101

Dear Ms. Dawson,

Enclosed is a Notification of Hazardous Waste Site located on our Long-view plant site, filed per Superfund Section 103(c). As part of our continuing review, we recently determined that such filing was necessary.

We regret that our previous effort to identify sites requiring such notification did not identify this site. Please let us know if we can be of any further assistance in this matter.

Sincerely,

Robert A. Anderson, Manager  
Environmental & Regulatory Affairs

RAA/cb

cc: Tom Steiner - Sort 43 (w/encl)  
S. A. Heller - CH 3D23 "  
Ken Johnson - Sort 43 "

encl

**RECEIVED**  
JUN 16 1982

PROGRAM DEVELOPMENT SECTION



# Notification of Hazardous Waste Site

United States  
Environmental Protection  
Agency  
Washington DC 20460

RECEIVED

AUG 10 '82

Solid Waste Mgmt. &  
EPA Region X

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

## A Person Required to Notify:

Enter the name and address of the person or organization required to notify.

Name WEYERHAEUSER COMPANY

Street P.O. Box 188

City LONGVIEW

State WASH Zip Code 98632

## B Site Location:

Enter the common name (if known) and actual location of the site.

Name of Site CHLOR-ALKALI PLANT - WEYERHAEUSER MILLSITE

Street INDUSTRIAL WAY

City LONGVIEW

County COWLITZ

State WASH Zip Code 98632

## C Person to Contact:

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.

Name (Last, First and Title) KEN JOHNSON - REGION ENVIRONMENTAL ENGINEER

Phone (206) 425-2150

## D Dates of Waste Handling:

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year) 1956

To (Year) 1974

## E Waste Type: Choose the option you prefer to complete

Option 1: Select general waste types and source categories. If you do not know the general waste types or sources, you are encouraged to describe the site in Item I—Description of Site.

### General Type of Waste:

Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.

1. ☐ Organics
2. ☐ Inorganics
3. ☐ Solvents
4. ☐ Pesticides
5. ☒ Heavy metals
6. ☐ Acids,
7. ☐ Bases
8. ☐ PCBs
9. ☐ Mixed Municipal Waste
10. ☐ Unknown
11. ☐ Other (Specify)

### Source of Waste:

Place an X in the appropriate boxes.

1. ☐ Mining
2. ☐ Construction
3. ☐ Textiles
4. ☐ Fertilizer
5. ☐ Paper/Printing
6. ☐ Leather Tanning
7. ☐ Iron/Steel Foundry
8. ☒ Chemical, General
9. ☐ Plating/Polishing
10. ☐ Military/Ammunition
11. ☐ Electrical Conductors
12. ☐ Transformers
13. ☐ Utility Companies
14. ☐ Sanitary/Refuse
15. ☐ Photofinish
16. ☐ Lab/Hospital
17. ☐ Unknown
18. ☐ Other (Specify)

Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).

### Specific Type of Waste:

EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located.

|      |
|------|
| D009 |
|      |
|      |
|      |
|      |
|      |
|      |
|      |
|      |
|      |
|      |

|  |
|--|
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |

|  |
|--|
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |

## Notification of Hazardous Waste Site

Side Two

## F Waste Quantity:

Place an X in the appropriate boxes to indicate the facility types found at the site.

In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.

In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

## Facility Type

1. ☐ Piles
2. ☐ Land Treatment
3. ☒ Landfill
4. ☐ Tanks
5. ☐ Impoundment
6. ☐ Underground Injection
7. ☐ Drums, Above Ground
8. ☐ Drums, Below Ground
9. ☐ Other (Specify) \_\_\_\_\_

## Total Facility Waste Amount

cubic feet 2000 cu. yds.

gallons \_\_\_\_\_

## Total Facility Area

square feet 45,000 ft<sup>2</sup>

acres \_\_\_\_\_

## G Known, Suspected or Likely Releases to the Environment:


Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☐ Known ☒ Suspected ☐ Likely ☐ None

Note: Items Hand I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

## H Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.



## I Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

Mercury cells were utilized in the production process from 1956-74. Periodic maintenance and cell replacement produced a variety of waste materials having a very slight mercury contamination. As these materials were generated, they were piled in two areas adjacent to the production operations (see locations on map above) and subsequently covered over with river dredge spoils. Two wells, supplying water for process use only, are located adjacent to the westernmost disposal site.

## J Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other".

Name

Tom Steiner

Street

Weyerhaeuser Co, P.O. Box 188

City

Longview

State

WA

Zip Code

98632

Signature

Tom Steiner

Date

5/4/82

- ☒ Owner, Present  
☒ Owner, Past  
☐ Transporter  
☒ Operator, Present  
☒ Operator, Past  
☐ Other





*Mike*  
*Wier*

**Weyerhaeuser Company**

Tacoma, Washington 98477  
(206) 924-2345

June 14, 1982

Ms. Linda Dawson  
Hazardous Waste Division  
Environmental Protection Agency  
Region X  
1200 Sixth Avenue  
Seattle, Wa., 98101

Dear Ms. Dawson,

Enclosed is a Notification of Hazardous Waste Site located on our Long-view plant site, filed per Superfund Section 103(c). As part of our continuing review, we recently determined that such filing was necessary.

We regret that our previous effort to identify sites requiring such notification did not identify this site. Please let us know if we can be of any further assistance in this matter.

Sincerely,

Robert A. Anderson, Manager  
Environmental & Regulatory Affairs

RAA/cb

cc: Tom Steiner - Sort 43 (w/encl)  
S. A. Heller - CH 3D23     "  
Ken Johnson - Sort 43     "

encl

**RECEIVED**  
JUN 16 1982

PROGRAM DEVELOPMENT SECTION